



If you intend to measure voltages between 0 - 100v use a separate power supply for the VA unit.